


- Svasatore - 100°
- Kegelsenker - 100°
- Verzinkboor - 100°
- Fraises à ébavurer et à chanfreiner - 100°

## G171

G171	▪	1.1	1.2	1.3	3.1	3.2	3.3	3.4	7.1	7.2	7.3	7.4				
	•	1.4	1.5	1.6	4.1	4.2	4.3	5.1	5.2	5.3	6.1	6.2	6.3	6.4	8.1	8.2

G171



G171



6.30 - 25.00

max d mm	min d mm	l <sub>2</sub> mm	l <sub>1</sub> mm	d <sub>2</sub> Øh <sub>9</sub> mm	z	G171
6.3	1.5	4.5	44	5	3	G1716.3
8.3	2.0	5.5	49	6	3	G1718.3
10.4	2.5	6.6	49	6	3	G17110.4
12.4	2.8	7.0	53	8	3	G17112.4
16.5	3.2	9.0	56	10	3	G17116.5
20.5	3.5	11.0	61	10	3	G17120.5
25.0	3.8	13.5	65	10	3	G17125.0