

TOP

SURFACE DRIVE

108 PEZZI

BUSSOLE SURFACE DRIVE




1/4"

1/2"



FERMEC
articolo

DESCRIZIONE

24108

**CASSETTA 108 PEZZI,
CHIAVI A BUSSOLA SURFACE DRIVE DA 1/4"
& 1/2"
+ BUSSOLE TORX - CHROM-VANADIUM
QUALITÀ EXTRA**

CARATTERISTICHE

- 13 Bussole da 1/4" surface drive: 4, 4.5, 5, 5.5, 6, 7, 8, 9, 10, 11, 12, 13, 14 mm
- 8 Bussole da 1/4" surface drive Lunghe: 6, 7, 8, 9, 10, 11, 12, 13 mm
- 5 Bussole da 1/4" Torx - E4, E5, E6, E8
- 2 Prolunghe da 1/4" - 75, 100 mm
- 1 Impugnatura porta bussole da 1/4"
- 1 Snodo 1/4"
- 1 Leva con quadro scorrevole da 1/4"
- 1 Cricchetto sgancio rapido da 1/4"
- 18 Bussole cromate da 1/4" con inserti:
 - 7 torx: TX8, TX 10, TX 15, TX20, TX25, TX27, TX30
 - 4 esagono - 3, 4, 5, 6 mm
 - 3 taglio - 4, 5.5, 6.5 mm
 - 2 Ph - 1, 2
 - 2 Pz - 1, 2
- 17 Bussole da 1/2" surface drive
10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 24, 27, 30, 32 mm
- 5 Bussole da 1/2" lunghe surface drive: 14, 15, 17, 19, 22 mm
- 8 Bussole da 1/2" Torx: E10, E11, E12, E14, E16, E18, E20, E24
- 1 Cricchetto sgancio rapido da 1/2"
- 2 Prolunghe da 1/2" - 125, 250 mm
- 2 Bussole per candele 1/2": 16, 21 mm
- 1 Snodo da 1/2"
- 1 Quadro scorrevole 1/2"
- 1 Adattatore - Quadro 1/2" - Porta inserti 5/16"
- 17 Inserti 5/16":
 - 5 esagono - 7, 8, 10, 12, 14 mm
 - 3 taglio - 8, 10, 12 mm
 - 2 Ph - 3, 4
 - 2 Pz - 3, 4
 - 5 Torx - T40, T45, T50, T55, T60
- 4 Chiavi maschio esagonali piegate: 1.27, 1.5, 2, 2.5 mm

RICAMBI

FERMEC
articolo

DESCRIZIONE

24108-V

CASSETTA VUOTA PER 24108/35108

SURFACE DRIVE

108 PEZZI

BUSSOLE SURFACE DRIVE




1/4"

1/2"



BGS
articolo

DESCRIZIONE

BGS 2287

**CASSETTA 108 PEZZI,
CHIAVI A BUSSOLA SURFACE DRIVE DA 1/4" & 1/2"
+ BUSSOLE TORX - CHROM-VANADIUM
QUALITÀ EXTRA**

CARATTERISTICHE

- comprende i seguenti utensili attacco 1/4":
 - 13 Bussole da 1/4" surface drive: 4, 4.5, 5, 5.5, 6, 7, 8, 9, 10, 11, 12, 13, 14 mm
 - 8 Bussole da 1/4" surface drive Lunghe: 6, 7, 8, 9, 10, 11, 12, 13 mm
 - 5 Bussole da 1/4" Torx - E4, E5, E6, E7, E8
 - 2 Prolunghe da 1/4" - 50, 100 mm
 - 1 Impugnatura porta bussole da 1/4"
 - 1 Snodo 1/4"
 - 1 Leva con quadro scorrevole da 1/4"
 - 1 Cricchetto sgancio rapido da 1/4"
 - 18 Bussole cromate da 1/4" con inserti:
 - 7 torx: TX8, TX 10, TX 15, TX20, TX25, TX27, TX30
 - 4 esagono - 3, 4, 5, 6 mm
 - 3 taglio - 4, 5.5, 6.5 mm
 - 2 Ph - 1, 2
 - 2 Pz - 1, 2
- comprende i seguenti utensili attacco 1/2":
 - 17 Bussole da 1/2" surface drive
10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 24, 27, 30, 32 mm
 - 5 Bussole da 1/2" lunghe surface drive: 14, 15, 17, 19, 22 mm
 - 8 Bussole da 1/2" Torx: E10, E11, E12, E14, E16, E18, E20, E24
 - 1 Cricchetto sgancio rapido da 1/2"
 - 2 Prolunghe da 1/2" - 125, 250 mm
 - 2 Bussole per candele 1/2": 16, 21 mm
 - 1 Snodo da 1/2"
 - 1 Quadro scorrevole 1/2"
 - 1 Adattatore - Quadro 1/2" - Porta inserti 5/16"
- 17 Inserti 5/16":
 - 5 esagono - 7, 8, 10, 12, 14 mm
 - 3 taglio - 8, 10, 12 mm
 - 2 Ph - 3, 4
 - 2 Pz - 3, 4
 - 5 Torx - T40, T45, T50, T55, T60
- 4 Chiavi maschio esagonali piegate: 1.27, 1.5, 2, 2.5 mm
- peso 6,5 kg

SET 1/2"